








#### POWER CONNECTOR




- 1 : Phase U
- 2 : Ground
- 3 : Phase W
- 4 : Phase V
- A : No connection
- B : No connection
- C, D : No connection


#### FEEDBACK CONNECTOR



#### ORIENTATION OF CONNECTORS



#### SHAFT END



Weight :

This document is the property of PARVEX Transmission as well as reproduction or copy is not permitted without written authorisation.

|               |          |                      |      |                      |  |  |  |  |  |
|---------------|----------|----------------------|------|----------------------|--|--|--|--|--|
| Drawn         | 21/04/99 | PB                   | Visa |                      |  |  |  |  |  |
| Modifications | c        | AM 20315 05/05/00 DL | f    | AM 21359 02/04/03 NV |  |  |  |  |  |
|               | b        | AM 20179 26/11/99 PB | e    | AM 21110 23/07/02 SP |  |  |  |  |  |
|               | g        | AM 22000 13/06/05 SP | d    | AM 20589 10/01/01 PB |  |  |  |  |  |



Scale

7:10



NX300

OUTLINE DRAWING

|              |   |   |   |   |   |   |
|--------------|---|---|---|---|---|---|
| Format       | F | E | S | G | I |   |
| A3           | x | x |   |   |   |   |
| 344167AE7000 |   |   |   |   |   | g |