



Star Connection



Delta Connection



WIRING DIAGRAM

DUAL VOLTAGE THREE PHASE MOTORS