






POWER CONNECTOR




- 1 : Phase U
- 2 : Ground
- 3 : Phase W
- 4 : Phase V
- A : No connection
- B : No connection
- C, D : No connection


FEEDBACK CONNECTOR



ORIENTATION OF CONNECTORS



SHAFT END



DIMENSIONS

	NX420	NX430
L Maxi	175	200
B	120	145

Weight :

This document is the property of PARVEX. Transmission as well as reproduction or copy is not permitted without written authorisation.

Drawn	16/12/99	JMB	Visa						
Modifications	c	AM 21012 19/03/02 RG	f	AM 21992 08/06/05 YG	e	AM 21359 02/04/03 NV	d	AM 21117 21/08/02 SP	
	b	AM 20589 05/01/01 RG							
	a	AM 20366 02/11/00 PR							

Scale
1:2



NX400
OUTLINE DRAWING

Format	F	E	S	G	I	
A3	x	x				
344178AE7000	f					