## 7. CERTIFICATE OF COMPLIANCE

## Certificate of Compliance

| Certificate Number | E302760-20090312 | Report Reference | E302760-20090203 | Issue Date | 2009 | March 12 |



Issued to: SSD PARVEX SAS

8 Avenue du lac 21000 DIJON France

This is to certify that representative samples of

USL/CNL - Brushless servo motors

Models EX310, EX420, EX430, EX620, EX630, EX 820, EX 840, EX 860 followed by U, followed by A through Z, followed by A through Z, followed by R, followed by I, followed by 1, followed by 0, or 5, followed by code 00 through 99, for use in Hazardous (Classified) Locations, Class I, Groups C & D.

Have been investigated by Underwriters Laboratories Inc.  $^3$  (UL) or any authorized licensee of UL in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety: Standard No. UL 674, 4th Ed., Rev. 2008-08-12, Electric Morors and Generators for Use in Division 1 Hazardous (Classified) Locations.

Standard No. CAN-CSA C22.2 No. 145-M1986 (restfirmed 1992), Motors and Generators for Use in Hazardous Locations

Additional Information: Voltage Ratings 230/400/480

Only those products bearing the UL Listing Mark for the US and Canada should be considered as being covered by UL's Listing and Follow-Up Service meeting the appropriate requirements for US and Canada.

The UL Listing Mark for the US and Canada generally includes the UL in a circle symbol with "C" and "US" identifiers the UL in a circle symbol with "C" and "US" identifiers the word "LISTED", a control number (may be alphanumeric) assigned by UL, and the product category name (product identifier) as indicated in the appropriate UL Directory

Look for the UL Listing Mark on the product

Issued by TaMinKIM

PROGRAMMENT RUSSEL FILIP

Tai Min KIM, Project Englisher
Ur, International Finance SA
Ary information and advantation mechanic Ur. Mark our
for quoton; in Finance, yet may tall 484,001 or 10 to 10. Rassell L. Fil.1P, Senior Engineer Staff
Ul. International Finance CA.
184 on behalf of Language International Language IVI.

PVD 3628 - 01 /2009